
Existing Conditions Report and Feasibility Study for the

Town of Weston and **Weston Public Schools**

~ Cost Estimate ~

Weston, Connecticut January 9, 2008

Town of Weston, CT



















SUMMARY

The Town of Weston and Board of Education retained Kaestle Boos Associates, Inc. to complete an evaluation and prepare an Existing Conditions Report for their facilities. KBA and consultants have surveyed the four schools in the District: Hurlbutt Elementary School, Weston Middle School, Weston High School and Weston Intermediate School. This study includes support buildings like the Central Office/Annex and Bus Garage. The Town buildings assessed are: The Town Hall/Police Fire Complex, the Library, two Transfer Stations, the Butler Aluminum Compactor and the New Public Town Garage. The purpose of this evaluation is to provide an overview of the original buildings, additions and sites, to identify items in need of repair or replacement. This report will assist the Town and Board of Education in budgeting for the most appropriate and cost effective measures to maintain the operation, integrity, and functionality of all these structures over a 5 to 10 year period.

The cost associated with the recommendations listed in the Existing Condition Reports has been summarized by building. The Estimated figures are based on comprehensive means to remedy the current issues and not to renovate as new the facilities. These costs are in 2008 dollars. A column ranking the recommendations in terms of priorities has been added to the Cost Estimate. The total cost of the Town and School facilities is as follows:

| HURLBUTT ELEMENTARY SCHOOL | \$7,147,069 |
|---|--------------|
| WESTON MIDDLE SCHOOL | \$24,959,252 |
| WESTON INTERMEDIATE SCHOOL-M/E/P/FP SYSTEMS | \$376,220 |
| WESTON HIGH SCHOOL | \$6,026,158 |
| CENTRAL OFFICE AND ANNEX | \$438,747 |
| BUS GARAGE | \$500,724 |
| TOWN HALL/POLICE FIRE COMPLEX | \$2,961,062 |
| LIBRARY | \$1,209,784 |
| TRANSFER STATION OFFICE GARAGE | \$7,605 |
| TRANSFER STATION 2 CAR GARAGE | \$119,399 |
| BUTTLER ALUMINUM BUILDING | \$3,042 |
| NEW PUBLIC TOWN GARAGE | \$241,079 |
| | |

Finally a priority system was developed to rank all the individual recommendations from 1-good to 5poor. The ranking system incorporates a one to ten year period of time that is used to help in determining a cap by when the issues must be resolved. This system can be used as tool by the Administrators to reassess on an annual basis what items would be resolved for next year as the funds become available.

| Kaesti | e h | 0005 | Asso | ciat | es, I | Inc. |
|--------|-----|------|------|------|-------|------|
| | | | | | | |

\$43,990,141

TOTAL COST

| | | | 1968/91 North House | 1932 South House | 1950 East House | 1997 Core Building | Total Building | *Priority Ranking |
|-----|--|--------|---------------------------|--|-------------------------|--------------------------|-------------------|----------------------|
| | 1/1 | Second | 16,478 | 0 | 0 | 0 | 16,478 | |
| | | First | 16,680 | 27,688 | 20,153 | 19,151 | 83,672 | |
| | | Lower | 1,708 | 0 | 2,153 | 1,913 | 5,774 | |
| | | | 34,866 | 27,688 | 22,306 | 21,064 | 105,924 | |
| 1 | Site Recommendations-widen existing and add new walkways | | 9,750 | 4,875 | 4.875 | ū | 19,500 | 3 |
| 2 | -Repair ADA Ramp | | | 2,000 | | | 2,000 | 4 |
| 3 | -Repair perimeter chainlink fencing | | 1,000 | 1,000 | 1,000 | 0 | 3,000 | 2 3 2 3 4 2 2 5 5 3 |
| 4 | -New chainlink fencing along Rte 57 | | 4,400 | | | | 4,400 | 3 |
| 5 | -Pave Staff/Teachers Parking Lot | | | | | 23,500 | 23,500 | 2 |
| 6 | -Install curtain drain east side | | | 32,500 | | | 32,500 | 3 |
| 7 | -Resurtace XXXXX | 15000 | | | | 30,000 | 30,000 | 3 |
| 8 | North Parking Lot Lighting Improvements | | 20,000 | 0 | 0 | 0 | 20,000 | 4 |
| 9 | -Surface Paving Miantenance & Report | | 6,000 | 4,500 | 5,100 | | 18,600 | 2 |
| 10 | Storm Water System | | 6,000 | 3,000 | 3,500 | 2,500 | 15,000 | 2 |
| 11 | West Stair Re-Construction | | 19,200 | | | | 19,200 | 5 |
| 12 | Area of Refuge Signage/Call Station | | 600 | | | | 600 | 5 |
| 13 | Automatic Sprinkler System & Ceiling Tile only | | 250,290 | 217,351 | 158 201 | 150,335 | 786,178 | |
| 14 | Flat Roof Repairs | | 84,000 | | | | 84,000 | 4 4 5 4 |
| 15 | Brick Veener & Control Joints | | 5,000 | 18,000 | 12,000 | 2,000 | 37,000 | 4 |
| 16 | Replacement of Doors & Frames (rated 20 mins) | | 33,550 | | | | 33,550 | 5 |
| 17 | Replacement of Door Hardware not meet ADA Hazards | | 3,575 | 2,200 | 1,375 | 0 | 7,150 | |
| 18 | ADA Door Recesses in conjunction with no. 6 above | | 11,050 | | | | 11,050 | 4 |
| 19 | Complete Exterior Door Replacement | | 6,000 | | | | 6,000 | 4 |
| 20 | Repair Damages Wall Surfaces | | 52,300 | 5,000 | 6,500 | 2,500 | 66,300 | 3 |
| 21 | Complete ACM Abatement (NIC Kitchen in No 16) | | 5,000 | 20,000 | 25,000 | | 50,000 | 4 |
| 22 | Stair Renovations to meet ADA | | 5,700 | 1,500 | 2,700 | 0 | 9,900 | 4 |
| 23 | Code Compliant Plumbing Facilities | | 63.000 | | | | 63,000 | 4 |
| 24 | New Bleachers & Gymnasium Equipment | | 55,000 | | | | 55,000 | 4 |
| 25 | Complete Mechanical, Electrical & Plumbing Recommendations #1 = 1 164 000 | | 636,500 | 1,017,000 | 846,500 | 51,500 | 2,551,500 | 5 |
| | #2 = 640,000 | | | | | | | |
| | #3 = 192,000 | | | | | | | |
| | #4 = 955,500 | | | | | | | |
| | #5 = 238,000 | | | | | | | |
| -26 | Renovation of Cafeteria & Kitchen | | | | 758.000 | | 750,000 | 4 |
| 27 | Relocation of Senior Center | | | Elsewhe | | | 0 | 3 |
| 41 | Relocation or Senior Center | - | 1,287,915 | The second secon | 1,816,751 | 265 335 | 4,698,928 | S20 |
| | Takes Takes Care | | CATAMATICA (A) | 210001280 | reference to the second | 200,000 | - and a large | |

Total Trade Cost

Note: To the above values Construction Burdens should be added for general conditions, contractors oh&p & bond of 17% depending on the delivery system

798,818

Indirect or Soft Cost should be added for professional fees, underwriting costs and contingencies exclusive of FF&E of 30%

1,649,324

Total 7,147,069

[.] Priority List

^{#1 =} Good (years 9 and 10) Minimal work is needed.

^{#2 =} Between fair and good (years 7 and 8) Deteriorated items not needing immediate repair/replacement

^{#3 =} Fair. (years 5 and 6) Not a code related issue, but much deteriorated item that needs attention #4 = Between fair and poor (years 3 and 4) Items with code issues such as handicapped compliance or otherwise needing more work and impacting other systems

^{#5 =} Poor (years 1 and 2) Life and Safety code issues, items which must be repaired/replaced immediately

| | | | 1966 Middle School | New Gym Pool | čotal Construction | *Priority List |
|------|--|---------------|--------------------------|-----------------|-----------------------------------|-------------------|
| | | Main Lower | 149.219 | 5 000 16 097 | 157,219 16,097 | |
| | | 1 | 149,219 | 24.097 | 173,316 | |
| | 5 e Recommendations-Accessibile Designates ADA Route | | 4.500 | | 4,500 | 4 |
| | Reconstruct as Pedestrian Walkways | | 18 500 | | 18,500 | 3. |
| | Report Stairs at NW Site | | 96,000 | | 36,000 | 3 |
| ă. | -Replace Wooden Guard of all NW corner of Site | | 6.240 | | 6,240 | 3 |
| | Provide hard-surfaced walkway from stairs in SW | | 1,000 | | 3,000 | 3 |
| | -Sione dust access to playing fields | | 1.675 | | 1,875 | 2 |
| | Acdin Carch Basins to Improve drainage | | 9-200 | | 9,200 | 2 |
| 4 | Receivede Courtyards into Lundscaping | 9.961 | 114,592 | | 114,552 | 3 |
| - | stolicing Envelope-Capit & Rapsi: PheCasi Concrete: | 4.080 | 16.726 | | 15,728 | 4 |
| -5 | Clean-Raptin & Parts Exterior Schill. | 9:600 | 95,040 | | 95,040 | 3 |
| | Clean Plant & Repair Brick Masonry | 20,400 | 112,200 | | 112,280 | 3 |
| 33 | Replace Extends Windows & Entiances | 6.528 | 592.932 | | 592,932 | 3 |
| 71 | Structural Repairs-General | | 75,000 | | 75,000 | 4 |
| 187 | -Gymnasum & Pool | | 0 | 500,000 | 200,000 | # |
| | High sceller sting skyrights & root memerane | | 2 100.000 | | 2,100,000 | 5 |
| 5 | Sear Composi Partivona to geck and at all pent ations | 5,190 | 27.300 | 10 March 200 | 27,300 | 5 |
| 7 | Install Automatic Sprinklers thoughout | | 517,657 | 148,197 | 1,065,893 | 3 |
| 1. | Recurse Lighting Fedure with energy effect models with item above | 78.971 | 715,222 | | 715,222 | * |
| 7.74 | Correct listence Disco'Frame Fire Ratings | 45 | 50,025 | | 56,025 | 5 |
| 29 | Correct Interior Gods Handwiste for ANSI & ADA | 25 | 9.125 | | 9,125 | 4 |
| 31 | Corner Door Geometry per ADA pushipul simenions | 24 | 18 400 | | 68,400 | 4 |
| | Repair replace at Damaged Surfaces | 358,126 | 03.292 | | 93,292 273.582 | 3 |
| | Repairs all was surfaces and Doors & Hardware | 358,126 | 273.562 | | 250,000 | 4 |
| 75 | Apple all AGM floor Re | 50,000 | 250.000 | | 241,000 | |
| 4.0 | New Sirean' Flooring for above | 50,000 | 241,000 25,680 | | 25,680 | |
| 20 | Co- loci devocacies in all stanways | 1 | 16,000 | | 16 000 | 2 |
| | Upginus Resolut Controls der ADA | 40 | 248,660 | | 248,000 | - 2 |
| 10 | Correct all ADA Tolet Facilities issues Add Plumbing Finiting to account for losses above and requirements | 54 | 324 300 | | 324,000 | 4 |
| 10 | Regar Regards & Referant Exerting Oxplay Cases | 6 | 27,000 | | 27,000 | 2 |
| 1 | Correct ADA non-compliant Casework/Plumbing | 54 | 367.360 | | 267,300 | 4 |
| 1 | Reprisce arraquated equipment of Technology Education Areas (No FF&E) | | 175 000 | | 275,000 | 4 |
| 33 | Regresse ADA non-upropulant appliances at Consumer Economics | | 45 000 | | 45,000 | 4 |
| 34 | Alternate for New Auditorium | 6,500 | 2 437,500 | | 2,437,500 | 3 |
| | Replace only Gymnasium Equipment & Beachers | | 145.000 | | 145,000 | 4 |
| 34 | Alternate to Renovate Old Comnasium less improvements above | 5,000 | 345,000 | | 345,000 | 4 |
| 13 | Alternate to enclose Library and improve Acoustics | 12,000 | 210,000 | | 210,000 | 4 |
| 101 | Renovate Heath Suite | 2,000 | 17 (.000 | | 174,000 | 6 |
| 32 | Resignate Kitzben and Refugsor Cafeteria | | 975,005 | | 875,000 | 5 |
| 40 | Fiel dyste Lower Level Locker Rooms | 0.000 | 1,135,200 | | 1,135,200 | 4 |
| 41 | Currer general refurbishments | 149,219 | 2,584,380 | | 2,984,380 | 3 |
| 47 | MEP Recommendations-OBR-Replace Existing Bollers | | 135.000 | | 135,000 | 3 |
| 43 | -New Craffs for each borrer | | 13,000 | | 13,000 | 5 |
| 4- | New Fuel Ol/Bland Pumps & Filters | | 7,000 | | 7,000 | 3 |
| 5 | NBH Weld return yakes | | 12,000 | | 42,000 | 4 |
| 450 | Replace qualified burners for improved contil | | 5,600 | | 2,600 | 2 |
| 47 | New Drafts for each boyer | | 15,000 | | 13,000 | 3 |
| +1 | -Right gerant leak Protection/Shut Down | | 16,000 | .0 | 16,000 | 5 4 |
| 25 | -Replace RTU for Science Wing | | 12,500 | | 20,2000 0.000 | 3 |
| 10 | -Reptace RTU for Wings: F. & 'G' | | 119,000 | | 110,000 | 5 |
| | -Reptade Pool Hy AC System | | 0 0 | | | 5 |
| | -Replace Mechill equipment & piping in Pool Filter Rim | | 23,000 | | 23,000 | 5 |
| 35 | remains Add emergency againg on exterior at exit agress | | 23,000 | | 23,000 | |
|)Æ | Adit Countyard emergency lighting | | 18 000 | | 18,000 | |
| | Add remote switching in New Gymnas-um-extenor to lighting panel | | 38 000 | | 36.000 | |
| | Approval battery power exit sign thoughout | | 7,000 | | 7,000 | |
| 31 | Phinning Reinave steam to domestic water heat exchangers -thronous in Old Boter Room water softened system | | 2,500 | | 2,500 | |
| | Connect Water Hielen device to 8MS | | 1,000 | | 1,000 | |
| 60 | -New gas fired domestic water heater system | | 54,000 | | | |
| | THE RESERVE OF THE PROPERTY OF | | 15,888,068 | | THE RESERVE AND PERSONS ASSESSED. | 41 |

Noise To the above values Construction Burdens should be added for general conditions, contractors of \$5 bond of 17% depending on the delivery system.

2,789,660

Indirect or Soft Cost should be added for professional fees, underwriting costs and conlingencies exclusive of FF&E of 30%

5,759,827

24,559,252 Total

^{*} Priority List

Financy List
 Financy List
 Food (years 9 and 10) Minimal work is needed
 Finance Fi

| | | 100 | |
|------|--|------------------------|------------------|
| | | Intermediate School | *Priority |
| | | 5611001 | LIST |
| 1 | Site recommendations-Re-install ADA Concrete Ramp | 1.000 | 4 |
| 2 | -Maintenance of Bark Mulch & Paving | 2.500 | 2 |
| 3 | -Install paved acess to bleachers. | 4,250 | 4 |
| 4 | Install accessible route to synthetic field | 5.100 | 4 |
| 5 | MEP Recommendations-Penhouse Ventilation | 5.000 | 4 |
| 6 | -New automatic glycol fill system for ACC-2 | 6.500 | 2 |
| 7 | -Rebalance all Air & Water Systems | 50,000 | 5 |
| 8 | -Realign Pump P-4 | 1.500 | 5 |
| 9 | -High Temperature Exhaust Fans for Data Closets (2) | 8.000 | 4 |
| 10 | -Repair remote fuel oil guage | 2.000 | 5 |
| 11 | -Egress Lighting by new bollard fixture | 6.500 | |
| 12 | Egress Lighting by batery backup change fixtures | 12.000 | 5 |
| 13 | -Update Panel Circuit Schedules | 25.000 | 5 5 5 5 |
| 14 | RemedyCode Clearances at Panel/Transformer Locations | 4,000 | 5 |
| 15 | -Smoke Detection to be install in Gym/Lib/Music 119 | 36,000 | 5 |
| 16 | -Update Fire Alarm Panel Circuit Schedules | 4,000 | 5 |
| 17 | Plumbing-Backflow Preventor-Domestic Water | 2.500 | 5 |
| 1.8 | -Add'l Hot Water Generation and Circulating Pumps; remove heat trace | 68,000 | 4 |
| 19 | Disconnect Automatic Make-Up Water System to Boilers | 1,000 | 5 |
| 20 | -Connect Water Meter Readings to BMS | 1,000 | 3 |
| 21 | -Add new Thermoststic Mixing Valve to Domestic Hot Water System | 1,500 | 4 |
| | Total Trade Cost | 247,350 | 3,00 |
| Note | To the above values Construction Burdens should be added for | | |
| | general conditions, contractors on&p & bond of 17% depending on | 70.000 | |
| | the delivery system | 42,050 | |
| | indirect or Soft Cost should be added for professional fees. | 86,820 | |
| | underwriting costs and contingencies exclusive of FF&E of 30% | | |
| | Total | 376,220 | |

[·] Priority List

^{#1 =} Good (years 9 and 10) Minimal work is needed.

^{#2 =} Between fair and good (years 7 and 8) Deteriorated items not needing immediate repair/replacement

^{#3 =} Fair. (years 5 and 6) Not a code related issue, but much deteriorated item that needs attention

^{#4 =} Between fair and poor (years 3 and 4) Items with code issues such as handicapped compliance or otherwise needing more work and impacting other systems.

^{#5 =} Poor (years 1 and 2) Life and Safety code issues, items which must be repaired/replaced immediately

| | * | First Floor Classrooms Music Rooms Gymnasium Support | 1966 High School 24,056 3,235 11,822 5,249 44,362 | *Priority Rating |
|----------|--|--|--|---------------------|
| 1 | Renovate Courtyards including Landscaping | 35,250 | 334,875 | 27 |
| 2 | Parking Lot Sensor Control | 00,200 | 24,000 | 3 |
| 3 | Sité Recommendations-Accessibile Designated ADA Route | | 2,500 | 4 |
| 5 | Widen North Side Pedestrian Walloway | | 3,500 | 4 |
| 6 | -ADA Designation | | 200 | 4 |
| 7 | Reset Catch Basins for Drainage | | 3,000 | 2 |
| 8 | Building Envelope-Clean & Repair PreCast Concrete | 4,800 | 19,680 | 4 |
| 9 | -Clean,Repair & Paint Exterior Soffit | 4.000 | 13,200 | 3 |
| 10 | Clean, Point & Repair Brick Masonry | 12,000 | 39,600 | 3 |
| 11 | -Replace Exterior Windows & Entrances -Roof Repairs-minor | 12,000 | 994,000 | 4 |
| 12 | Abate all ACM floor tile | | 3,000 | 3 |
| 13 | ADA Compliance Tollels | 15,000 | 75,000 | 4 |
| 1.4 | -Door Entrances & Hardware | 4 | 88,000 | 4 |
| 15 | Reptace Interior Doors (100%) & Frames (20%) | 12 | 15,000 | 4 |
| 15 | Refurbish all-wall surfaces | 90 | 81,810 | 4 |
| 1.7 | -floor surfaces | 110,000 | 192,500 | 3 |
| 18 | Accountical Ceilings & Lights in Classrooms & Corridors | 40,000 | 208,800 | 4 |
| 19 | Acoustical Treatment in MEP Areas | 28,000 2,750 | 341,600 | 4 |
| 20 | Renovate Gymnasium incl Bleachers & Equipment | 11.822 | 9,625 | 4 |
| 21 | Replace all lockers | 600 | 120,000 | 4 |
| 22 | Renovate Music Rooms including tiered seating/standing | 3,235 | 223,215 | 4 |
| 23 | MEP Recommendations-Exhaust Draft Fans | 4,600 | 5,000 | 4 |
| 24 25 | -Adjust Existing Burners for Controlled Fire | | 3,600 | 4 |
| 26 | Replace Fuel Oil/Blend Pumps & Filters | | 20,000 | 4 |
| 27 | Replace Glycol type ethlene with proc | | 17,000 | 3 |
| 28 | -Tie-In to Campus BMS | | 1,000 | 3 |
| 29 | Air Conditiong for Classrooms (16) | | 94,000 | 2 |
| 38 | New Air Systems for Dance Studio | | 12,500 | 3 |
| 31 | -C-5 & C-6 Rooms | | 16,000 | 5 |
| 32 | Add Cooling Calil for RTU Wing 'C' | | 12,500 | 3 |
| 33 | Re-balance Guidance Wing Healing Replace Nat'l Gas Emerg Gen with Diesel Fuel | | 3,000 | 5 |
| 34 | - Video Monitors in Corndors | | 65,000 | 5 |
| 35 | -Install Classroom Occupancy Sensors | | 20,000 | 4 |
| 36 | New Lighting-Calé, Library, Art Room | 40 | 25,000 | 4 |
| 37 | Minor Power & Lighting Renauce | | 25,000 | 3 |
| 38 | Fire Alarm-low Exit Signs place of Assembly | | 5,000 | 3 |
| 39 | -realign beam detectors | 1 | 2,500 | 5 |
| 40 | Plumbing-Backflow Preventor-Domestic Water | | 2,000 | 5 |
| 41 | Install thermostatic mixing valve for ever wash station. | | 2,500 | 5 |
| 42 | -Replace damaged Drinking Fountain | | 2,500 | 5 |
| | Total Trade Cost | 3, | 2,250 961,971 | ā |
| iole | For the above values Construction Burdens should be added for general conditions, contractors on \$p.8 bond of 17% depending on the delivery system. | | | |
| | 0.0545000 | | 673,535 | |
| | Indirect or Soft Cost should be added for professional fees, | | | |
| | underwhiling costs and contingencies exclusive of FF&E of 30% | 1, | 390,652 | |
| | | Total 6. | 026,158 | |

Priority List

Priority Lis!
 #1 = Good (years 9 and 10) Minimal work is needed.
 #2 = Between fair and good (years 7 and 8) Deteriorated items not needing immediate repair/replacement #3 = Fair (years 5 and 6) Not a codo related issue, but much deteriorated item that needs attention.
 #4 = Between fair and poor (years 3 and 4) Items with code issues such as handicapped compliance or otherwise needing more work and impacting other systems.
 #5 = Poor (years 1 and 2) Life and Safety code issues, items which must be repaired/replaced immediately.

Central Office-Annex Weston, CT

Kaestle Boos Associates

| | | Attic First Basement | 1997 Central Office 3,851 4,000 3,851 11,702 | 2001 Annex 0 3,851 0 3,851 | | *Priority Rating |
|-------|--|----------------------------|--|---|---------|---------------------|
| 78 | Repair Bituminous Paving & Curbs | 12000 | | | 38,220 | 3 |
| 2 | ADA Provisions and Accessibility to building & playground | -2000 | | | 4,500 | |
| 3 | Concrete Walkway Repair by replacement | 600 | | | 7,200 | 3 |
| 4 | ADA Compliance-Toilet Facilies (2) | Section 1 | 21,000 | 21.000 | 42,000 | 4 |
| 5 | Repair and or Replace Exterior Wood Railing | | 3,000 | | 3,000 | 3 |
| 6 | Replace previously patched floor tile | | 0 | 600 | 600 | 3 |
| 7 | MEP Recommendations-Combustion Air w/ Motorized Dampers | | 4,000 | 3,000 | 7.000 | 5 |
| 8 | -Insulate Hot Water Piping | | 15,000 | 0 | 15,000 | 5 |
| 9 | -Convert each AHU to VAV | | 27,000 | 23,000 | 50,000 | 43433553235435452 |
| 10 | Automate Glycol System to Hot Water | | 4,000 | 3,500 | 7,500 | 2 |
| 11 | -Tie-In to Campus BMS | | 5,000 | 5,000 | 10,000 | 3 |
| 12 | -Improved Fire Alarm Detection | | 4,250 | | 4,250 | 5 |
| 13 | -Additional Lighting at Exit Door | | 2,000 | | 2,000 | 4 |
| 14 | -Install Occupancy Sensors | | 0 | 10,000 | 10,000 | 3 |
| 15 | -Emergency Lighting at Swichgear | | | 1,000 | 1,000 | 5 |
| 16 | Control Domestic Hot Water Temperature | | | 1,500 | 1,500 | 4 |
| 17 | -Backflow Preventor at Dom Water | | | 2,500 | 2,500 | 5 |
| 18 | Automatic Fire Protection System | | 60,287 | 21,903 | 82,190 | 2 |
| | Total Trade Cos | | 145,537 | 93,003 | 288,460 | |
| Note: | To the above values Construction Burdens should be added for general conditions, contractors oh&p & bond of 17% depending on the delivery system | | | | 49,038 | |
| | Indirect or Soft Cost should be added for professional fees, underwriting costs and contingencies exclusive of FF&E of 30% | | | | 101,249 | |

· Prionty List

#1 = Good (years 9 and 10) Minimal work is needed

#2 = Between fair and good (years 7 and 8) Deteriorated items not needing immediate repair/replacement

Total 438,747

#3 = Fair: (years 5 and 6) Not a code related issue, but much deteriorated item that needs attention.

#4 = Between fair and poor (years 3 and 4) Items with code issues such as handicapped compliance or otherwise needing more work and impacting other systems.

| | | | 1953/76 | *Priority |
|---|---|---------------|--|---|
| | 2 | | Bus Garage | List |
| | | First ower | 4,282 0 4,282 | |
| 1 2 3 4 5 6 7 8 9 10 11 12 13 | New Total Bituminous Paving Replacement Guardrail Separartion & Retaining Wall Reconstruction Building Envelope-Window Replacement -Masonry Joint Repairs -Roofing-Minor Repairs -Wood Trim & Cupola Repairs/Painting ADA Compliance-Toilet/Shower Facility -Doors & Hardware Refurbish Interior Surfaces-Walls -Floors Improved Office Air Conditioning Backflow Preventor-Dom. Water Automatic Fire Protection System | 50,000 | 129,600 18,000 32,100 5,000 3,500 3,750 40,000 3,000 13,950 13,750 15,000 2,500 27,058 | 3 3 3 1 3 4 4 3 3 4 5 2 3 |
| 14 | Normal & Life Safety Lighting Improvents Total Trade Cost | | 22,000 329,207 | 3 |
| Note | To the above values Construction Burdens should be added for general conditions, contractors oh&p & bond of 17% depending on the delivery system Indirect or Soft Cost should be added for professional fees, underwriting costs and contingencies exclusive of FF&E of 30% | | 55,965 115,552 | |
| | | Tota | 500,724 | |

^{*} Priority List

#1 = Good (years 9 and 10) Minimal work is needed.

#2 = Between fair and good (years 7 and 8) Deteriorated items not needing immediate repair/replacement

#3 = Fair: (years 5 and 6) Not a code related issue, but much deteriorated item that needs attention.

#4 = Between fair and poor (years 3 and 4) Items with code issues such as handicapped compliance or otherwise needing more work and impacting other systems.

| | | | 1952/86 Town Hall | 1952/86 Police | 1963/86 Fire | 1963 Comm. Center | Total Building | *Priority |
|-----|--|---------|-------------------------|-------------------|-----------------|-------------------------|-------------------|-----------------|
| | | Second | Ö | 0 | 5,790 | 0 | 5.790 | 2101 |
| | | First | 7,737 | 1,242 | 7.062 | 723 | 16,764 | |
| | | Lower | 2,865 | 4,530 | 0 | 0 | 7,395 | |
| | | 3000000 | 10,602 | 5,772 | 12,852 | 723 | 29,949 | |
| 1 | Site ADA Parking & Accessible Routes | 15 | | | | | 3,750 | 4 |
| 2 | -Pavement Replacement Incl Curbing | 64600 | | | | | 174,730 | 3 |
| 3 | New Drainage Structrures and Adjustments to Existing | 3 | | | | | 27,000 | 5 |
| 4 | New Concrete Stair at rear of Police | 100 | | 15,000 | | | 15,000 | 4 |
| 5 | Building Envelope-Roofing | | 510,000 | 40,000 | 15,000 | 2,000 | 567,000 | |
| 6 | -Exterior Drainage-Walter Infiltration | | 30.000 | 35,000 | 5.000 | 5.000 | 75,000 | 6 |
| 7 | -Caulking Masonry Joints | | 7,000 | 5,000 | 6,500 | 1,000 | 19,500 | 1 |
| 8 | -Masonry Re-Pointing | | 10.000 | 5,000 | 7.500 | 1,500 | 24,000 | 3 |
| 9 | -Replacement Windows | | 74,000 | 16.000 | 48.700 | 0 | 138,700 | 5 3 3 |
| 10 | ADA Compliance-Toilets & turning Radii | | 75.000 | 25,000 | 25.000 | 12,000 | 137,000 | 4 |
| 1.1 | -Stairs & Floor Level Changes | | 19,000 | 7,500 | 8,000 | 0 | 34,500 | 4 |
| 12 | -Door Hardware & Geometery | | 23 000 | 15,200 | 10,000 | 800 | 49,000 | 7 |
| 13 | -Entrances | | 15.000 | 10,000 | 0 | 0 | 25,000 | 4 |
| 14 | -Second Floor ADA Accessibility | | 0 | 0 | 60,000 | 0 | 60,000 | 4 |
| 15 | Additional Sorage Areas-separated from MEP Areas | | 5.000 | | | | 6,000 | 4 |
| 16 | Repair Damages Wall Surfaces & General Refurbishment | | 95,400 | 52,000 | 64,200 | 4,300 | 215,900 | 4 |
| 17 | ACM Abatement | | 18,000 | 18,000 | 5.000 | 1,500 | 42,500 | 4 |
| 18 | MEP Recommendations-AC Condensing Unit Replacement | | 7.000 | in Town Hall | 0 | 0 | 7,000 | 3 |
| 19 | Boller Replacement w/ accessones | | 45,000 | in Town Has | 0 | 0 | 45,000 | 4 |
| 20 | -Hot Water Pipe Covering | | 60,000 | in Town Hall | 0 | 0 | 60.000 | 4 |
| 21 | -Exit Lights Low Places of Assembly | | 2,000 | 0 | 0 | 0 | 2,000 | 6 |
| 22 | -Improved Emergency Lighting | | 2,000 | 0 | 0 | 0 | 2,000 | 5 |
| 23 | -GFI Outlets in Wet Areas | | 500 | 350 | 0 | 0 | 850 | 6 |
| 24 | -Call for Aid at ADA Toilets | | 2,000 | 3,000 | 3,500 | 2,500 | 11,000 | 5 5 5 5 5 5 5 5 |
| 25 | -Additional Smoke Detection | | 0 | 2,750 | .0 | 0 | 2,750 | 5 |
| 26 | -Backflow Preventor-Dom Water | | 2,000 | 0 | 0 | 0 | 2,000 | 5 |
| 27 | Automatic Fire Protection System | | 84,655 | 37,807 | 70,686 | 5,459 | 198,606 | 2 |
| | Total Trade Cos | t | 1,087,555 | 288,607 | 329,086 | 36,059 | 1,946,786 | |

Note. To the above values Construction Burdens should be added for general conditions, contractors oh&p & bond of 17% depending the delivery system

indirect or Selt Cost should be added for professional fees. underwriting costs and contingencies exclusive of FF&E of 30%

Total 2,961,062

330,954

683,322

* Priority List

#1 = Good (years 9 and 10) Minimal work is needed

#2 = Between fair and good (years 7 and 8) Deteriorated items not needing immediate repair/replacement

#3 = Fair: (years 5 and 6) Not a code related issue, but much deteriorated item that needs attention

#4 = Between fair and poor (years 3 and 4) Items with code issues such as handicapped compliance or otherwise needing more work and impacting other systems.

#5 = Poor (years 1 and 2) Life and Safety code issues, items which must be repaired/replaced immediately

| | | | 1963/85/94 | |
|------|--|-------|----------------------------------|-----------------------|
| | Mez Firs Low | | 1,055 12,313 784 14,152 | *Priority List |
| 1 | Site-ADA Parking & Accessible Routes | 5 | 1,250 | 52 |
| 2 | -Pavement Replacement incl Curbing | 25000 | 67,750 | 3 |
| 3 | -New Drainage Structrures and Adjustments to Existing | 1 | 9,000 | 2 |
| 4 | Window Replacement-no 1994 Addition | - 3 | 126,126 | 4 |
| 5 | Exterior Door Replacement & or Repair-no 1994 Addition | | 19,080 | 4 |
| 6 | Stone Wall Crack Repair | | 7,500 | 3 |
| 7 | Exterior Soffits Repair | | 16,380 | 4 |
| 8 | Exterior Lighting Improvement | | 17,000 | 5 |
| 9 | Door Hardware & ADA Compliance | | 4,920 | 4 |
| 10 | Interior Re-painting | | 27,440 | 2 |
| 11 | Damaged Ceiling Tile Repacement (15%) | | 4,000 | 3 |
| 12 | Floor Tile ACM Abatement (w/10 below) | | 35,000 | 4 |
| 13 | Floor Finishes Replacement | | 60,000 | 3 |
| 14 | Lighting Fixture Replacement | | 40,000 | 3 |
| 15 | ADA Reception Desk Provisions | | 5,000 | 4 |
| 16 | Complete MEP Recommendations-Glycol feed System | | 5,000 | 3 |
| 17 | -Fire Alarm & Detection | | 37,500 | |
| 18 | -Emergency Lighting | | 40,000 | 5 5 2 5 4 |
| 19 | -Backflow Preventor-Dom, Water | | 2,500 | ., |
| 20 | Complete Automatic Sprinkler System | | 62,000 | 3 |
| 21 | Roof Replacement & Accessories | | 168,000 | 2 |
| 22 | Accessible Mezzanine Access | | 40,000 | 4 |
| | Total Trade Cost | - | 795,446 | -4 |
| Note | To the above values Construction Burdens should be added for general conditions, contractors oh&p & bond of 17% depending on the delivery system Indirect or Soft Cost should be added for professional fees, underwriting costs and contingencies exclusive of FF&E of 30% | | 135,226 | |
| | | Total | 1,209,784 | |

[·] Priority List

^{#1 =} Good (years 9 and 10) Minimal work is needed.

^{#2 =} Between fair and good (years 7 and 8) Deteriorated items not needing immediate repair/replacement

^{#3 =} Fair: (years 5 and 6) Not a code related issue, but much deteriorated item that needs attention.

^{#4 =} Between fair and poor (years 3 and 4) Items with code issues such as handicapped compliance or otherwise needing more work and impacting other systems.

^{#5 =} Poor (years 1 and 2) Life and Safety code issues, items which must be repaired/replaced immediately

| | | | 1972 Office Garage | 1972 Two (2) Car Garage | Total Buildings | *Priority List |
|-------|--|---------|--------------------------|-------------------------------|--------------------|-------------------|
| | | First | 720 | 600 | 1,320 | |
| | | Lower | | 0 | 0 | |
| | Office/Garage | | 720 | 600 | 1,320 | |
| 1 | Building Envelope-masonry walls & wood trim | | 7,500 | | 7 500 | |
| 2 | ADA provision-Accessible Toilet | | 6,500 | | 7,500 6,500 | 3 |
| 3 | Emergency Lighting | | 4,000 | | 4,000 | -6 |
| 4 | Automatic Sprinkler System-off Domestic Service | | 5,000 | | 5,000 | 5 2 |
| Note: | To the above values Construction Burdens should be added general conditions, contractors oh&p & bond of 17% depend the delivery system | | | | 850 | |
| | Indirect of Soft Cost should be added for professional fees, underwriting costs and contingencies exclusive of FF&E of 3 | 10% | | | 1,755 | |
| | | | | Total | 7,605 | |
| | Two (2) Bay Garage Demolish & Reconstruction a firm foundation Automatic Sprinkler System-off Domestic Service | | | 49,000 | 49,000 | 5 |
| 2 | Total Trai | de Cost | 23,000 | 6,500 55,500 | 6.500 88.710 | 2 |
| Note: | To the above values Construction Burdens should be added general conditions, confractors oh&p & bond of 17% depend the delivery system | | 6 | 00000 | 13,345 | |
| | | | | | 19,040 | |
| | Indirect or Soft Cost should be added for professional fees, underwriting costs and contingencies exclusive of FF&E of 3 | 10% | | | 27,554 | |
| | | | | Total | 119,399 | |

^{*} Priority List

^{#1 =} Good (years9 and 10) Minimal work is needed.

^{#2 =} Between fair and good (years 7 and 8) Deteriorated items not needing immediate repair/replacement

^{#3 =} Fair: (years 5 and 6) Not a code related issue, but much deteriorated item that needs attention.

^{#4 =} Between fair and poor (years3 and 4) Items with code issues such as handicapped compliance or otherwise needing more work and impacting other systems.

^{#5 =} Poor (years 1 and 2) Life and Safety code issues, items which must be repaired/replaced immediately

| | | | 1982 | Total Building | Priority |
|------|--|-------|-------|-------------------|----------|
| | | First | 600 | 600 | |
| | | Lower | 600 | 600 | |
| | Office/Garage | | | | |
| 1 | Building Envelope-misc repairs | | 2,000 | 2,000 | 3 |
| | Total Trade Cos | t | 2,000 | 2,000 | |
| Note | To the above values Construction Burdens should be added for general conditions, contractors oh&p & bond of 17% depending | | | | |
| | on the delivery system | | | 340 | |
| | Indirect or Soft Cost should be added for professional fees, underwriting costs and contingencies exclusive of FF&E of 30% | | | 702 | |
| | | | Total | 3,042 | |

Priority List

#1 = Good (years 9 and 10) Minimal work is needed.

#2 = Between fair and good (years 7 and 8) Deteriorated items not needing immediate repair/replacement

#3 = Fair: (years 5 and 6) Not a code related issue, but much deteriorated item that needs attention.

#4 = Between fair and poor (years 3 and 4) Items with code issues such as handicapped compliance or otherwise needing more work and impacting other systems.

| | | | 1997 | *Delevie |
|-----------------------|---|-----|---------|---------------------------------|
| | | | | *Priority List |
| | Attic | | 1,388 | List |
| | First | | 11.983 | |
| | Lower | | 0 | |
| | | - | 13,371 | |
| | Office/Garage | | | |
| 1 | Building Envelope-Overhead Door Crack Repair | | 25,000 | 3 |
| 2 | -Mold Abatement, Water Intrusion & Sealing | | 30,000 | |
| 2 3 4 | ADA Provisions-Toilet & Shower Facilities | | 15,000 | 3 4 4 3 5 5 5 |
| | -Kitchen Facility | | 3,000 | 4 |
| 5 6 7 8 9 | Minor Roof Repairs-Cupola & Shed Roof | | 2,500 | 3 |
| 6 | Fuel Oil Leak to Underground Tank | | 10,000 | 5 |
| 7 | Emergency Lighting throughout facility | | 12,000 | 5 |
| 8 | Backflow Preventor at domestic water supply | | 3,000 | 5 |
| 9 | Automatic Fire Protection System | | 58,000 | 2 |
| | Total Trade Cost | | 158,500 | |
| Note: | To the above values Construction Burdens should be added for general conditions, contractors oh&p & bond of 17% depending | | | |
| | on the delivery system | | 26,945 | |
| | Indirect or Soft Cost should be added for professional fees, | | | |
| | underwriting costs and contingencies exclusive of FF&E of 30% | | 55,634 | |
| | То | tal | 241,079 | |

^{*} Priority List

#1 = Good (years 9 and 10) Minimal work is needed.

#2 = Between fair and good (years 7 and 8) Deteriorated items not needing immediate repair/replacement

#3 = Fair: (years 5 and 6) Not a code related issue, but much deteriorated item that needs attention.

#4 = Between fair and poor (years 3 and 4) Items with code issues such as handicapped compliance or otherwise needing more work and impacting other systems.

Priority # 5 = Poor (years 1 and 2). Life and Safety code issues, Items which must be repaired/replaced immediately

| Hurlbutt Elementary School | North | South | East | Core | Total |
|---|---------|-----------|----------------|------------|-----------|
| | House | House | House | Building | Building |
| West Stair Re-Construction | 19,200 | 0 | | 0 | 19,200 |
| Area of Refuge Signage/Call Station | 600 | 0 | 0. | 0 | 600 |
| Replacement of Doors & Frames (rated 20 mins) | 636,500 | 1,017,000 | 846,500 | 51,500 | 2,551,500 |
| Complete Mechanical, Electrical & Plumbing Recommendations | | | | | 238,000 |
| SUBTOTAL | | | | | 2,809,300 |
| Weston Middle School | | | 1966 | New Gym | Total |
| | | | Middle School | Pool | |
| Replace existing skylights & roof membrane | | 0 | 2,100,000 | () | 2,100,000 |
| Seal Corridor Partitions to deck and at all pentrations | | 5.190 | 27,300 | 0 | 27,300 |
| Correct Interior Door/Frame Fire Ratings | | 45 | 56,025 | 0 | 56,025 |
| Renovate Kitchen and Refurbish Cafeteria | | | 875,000 | 0 | 875,000 |
| New Drafts for each boiler | | | 13,000 | 0 | 13,000 |
| Refrigerant leak Protection/Shut Down | | | 16,000 | | 16,000 |
| Replace Pool HVAC System | | | 0 | 160,000 | 160,000 |
| Replace Mech'l equipment & piping in Pool Filter Rsn. | | | 0 | 13,500 | 13,500 |
| Electrical-Add emergency lighting on exterior at exit egress | | | 23,000 | 0 | 23,000 |
| | | | 23,000 | 0 | 23,000 |
| Add Courtyard emergency lighting | | | 36,000 | 0 | 36,000 |
| Additional battery power exit sign thoughtout | | | 344,000 | 18 | 3,342,825 |
| SUBTOTAL | | | | | |
| Weston Intermediate School | | | | | Total |
| Re-balance all Air & Water Systems | | | | | 50,000 |
| Re-align Pump P-4 | | | | | 1,500 |
| Repair remote fuel oil guage | | | | | 2,000 |
| gress Lighting by new bollard fixture | | | | | 6,500 |
| Egress Lighting by battery backup change fixtures | | | | | 12,000 |
| Update Panel Circuit Schedules | | | | | 25,000 |
| RemedyCode Clearances at Panel/Transformer Locations | | | | | 4,000 |
| Smoke Detection to be install in Gym/Lib/Music 119 | | | | | 36,000 |
| Update Fire Alarm Panel Circuit Schedules | | | | | 4,000 |
| Plumbing-Backflow Preventor-Domestic Water | | | | | 2,500 |
| | | 90 | | | 1,000 |
| Disconnect Automatic Make-Up Water System to Boilers SUBTOTAL | | | | | 144,500 |
| | | | | | Total |
| Weston High School - 1966 Building | | | | | 16,000 |
| C-5 & C-6 Rooms. | | | | | 3,000 |
| Re-balance Guidance Wing Heating | | | | | |
| Replace Nat'l Gas Emerg Gen with Diesel Fuel | | | | | 65,000 |
| Fire Alarm-low Exit Signs place of Assembly | | | | | 2,500 |
| realign beam detectors | | | | | 2,000 |
| Plumbing-Backflow Preventor-Domestic Water | | | | | 2,500 |
| Install thermostatic mixing valve for eye wash station | | | | | 2,500 |
| Replace damaged Drinking Fountain | | | | | 2.250 |
| SUBTOTAL. | | | | | 95,750 |
| Central Office - Annex | | | Central Office | 2001 Annex | Total |
| MEP Recommendations-Combustion Air w/ Motorized Dampers | | | 4,000 | 3,000 | 7,000 |
| | | | 15,000 | 0 | 15,000 |
| Insulate Hot Water Piping | | | 4,250 | 0 | 4,250 |
| Improved Fire Alarm Detection | | | 7,620 | 1,000 | 1,000 |
| Emergency Lighting at Swichgear | | | | 2,500 | 2,500 |
| Backflow Preventor at Dom. Water | | | | 44700 | |
| SUBTOTAL | | | | | 29,750 |

| Bus Garage | | | | | - | Total |
|--|-----|-----------|--------------|-------------|--------------|-----------|
| Backflow Preventor-Dom. Water | | | | | | 2,500 |
| Town Hall/Police Fire Complex | | 1952/86 | 1952/86 | 1963/86 | 1963 | Total |
| 10wit Hain Fonce Fire Complex | | Town Hall | Police | Fire | Comm. Center | |
| New Drainage Structrures and Adjustments to Existing | | | | | | 27,000 |
| Building Envelope-Roofing | | 510,000 | 40,000 | 15,000 | 2,000 | 567,000 |
| Exterior Drainage-Water Infiltration | | 30,000 | 35,000 | 5,000 | 5,000 | 75,000 |
| Hot Water Pipe Covering | | 60,000 | in Town Hall | 0 | 0 | 60,000 |
| Exit Lights Low Places of Assembly | | 2,000 | .0 | 0 | 0 | 2,000 |
| mproved Emergency Lighting | | 2,000 | 0 | 0 | 0 | 2,000 |
| GFI Outlets in Wet Areas | | 500 | 350 | .0 | 0 | 850 |
| Call for Aid at ADA Toilets | | 2,000 | 3,000 | 3,500 | 2,500 | 11,000 |
| Additional Smoke Detection | | 0 | 2,750 | 0 | 0 | 2,750 |
| Backflow Preventor-Dom. Water | | 2,000 | 0 | .0 | 0: | 2,000 |
| SUBTOTAL | | | | | | 749,600 |
| . 6. 20.20 | | | | | | Total |
| Library | | | | | | 17,000 |
| Exterior Lighting Improvement | | | | | | 37,500 |
| Emergency Lighting Fire Alarm & Detection | 70 | | | | | 40,000 |
| Backflow Preventor-Dom. Water | 5.0 | | | | | 2:500 |
| ###################################### | | | | | | 168,000 |
| Roof Replacement & Accessories | | | | | 1 | 265,000 |
| SUBTOTAL | | | | | | |
| Transfer Station Office/Garage | | | | Office | Two (2) Car | Total |
| Transfer Station Office Garage | | | | Garage | Garage | Buildings |
| Emergency Lighting | | | | 4,000 | 0 | 4,000 |
| Demolish & Reconstruct on a firm foundation | | | | | 49,000 | 49,000 |
| SUBTOTAL | | | | | | 53,000 |
| Butler Aluminum Building | | | | | | |
| New Public Town Garage | | | | | | Total |
| Fuel Oil Leak to Underground Tank | | | i. | | | 10,000 |
| Emergency Lighting throughout facility | | | | | | 12,000 |
| Backflow Preventor at domestic water supply | | | | | | 3,000 |
| SUBTOTAL | | | | | | 25,000 |
| | | | | Total Amour | | 7.546.97 |

Priority # 4 = Between fair and poor (years 3 and 4) Items with code issues such as handicapped compliance or otherwise needing more work and impacting other systems

| fuributt Elementary School | North | South | East | Core | Total |
|---|--------------|--------|---------------|----------|-----------|
| tuributt Elementary Sensor | House | House | House | Building | Building |
| Repair ADA Ramp | | 2,000 | 0 | 0 | 2,000 |
| North Parking I or Lighting Improvements | 20,000 | 0 | .0 | 0 | 20,000 |
| | 84,000 | 0 | 0 | () | 84,000 |
| Flat Roof Repairs | 5,000 | 18,000 | 12,000 | 2,000 | 37,000 |
| Brick Veener & Control Joints | 3,575 | 2,200 | 1,375 | 0 | 7,150 |
| Replacement of Door Hardware not meet ADA Hazards | 11,050 | 0 | 0. | 0 | 11,050 |
| ADA Door Recesses in conjunction with no. 6 above | 6,000 | 0 | 0 | 0 | 6,000 |
| Complete Exterior Door Replacement | 5,000 | 20,000 | 25,000 | 0 | 50,000 |
| Complete ACM Abatement (NIC Kitchen in No.16) | 5,700 | 1,500 | 2,700 | () | 9,900 |
| Stair Renovations to meet ADA | 63,000 | 0. | 0 | 0 | 63,000 |
| Code Compliant Plumbing Facilities | 55,000 | 0 | 0 | 0 | 55,000 |
| New Bleachers & Gymnasium Equipment | aranga arang | 50 | | | 955,500 |
| Complete Mechanical, Electrical & Plumbing Recommendations | | | | | 1,300,600 |
| SUBTOTAL | | | | | |
| | | | 1966 | New Gym | Total |
| Weston Middle School | | | Middle School | Pool | |
| | | | 4,500 | 0 | 4,500 |
| Site Recommendations-Accessibile Designated ADA Route | | 1,080 | 16,728 | 0 | 16,728 |
| Building Envelope-Clean & Repair PreCast Concrete | | 40,000 | 75,000 | 0 | 75,000 |
| Structural Repairs-General | | | 0 | 200,000 | 200,000 |
| Gymnasium & Pool | | | 715.222 | 0 | 715,222 |
| Replace Lighting Fixture with energy efficit models with item above | | 263 | 9,125 | 0 | 9,125 |
| Correct Interior Door Hardware for ANSI & ADA | | 250 | 68,400 | 0 | 68,400 |
| Correct Door Geometry per ADA push/pull dimensions | | 240 | 250,000 | 0 | 250,000 |
| Abate all ACM floor tile | | 50,000 | 241,000 | 0 | 241,000 |
| New 'Green' Flooring for above | | 50,000 | 25,680 | 0 | 25,680 |
| Corrrect deficencies in all stairways | | 4 | C22878185555 | 0 | 16,000 |
| Upgrade Elevator Controls per ADA | | 100 | 16,000 | 0 | 248,000 |
| Correct all ADA Toilet Facilities Issues | | 40 | 248,000 | 0 | 324,000 |
| Add Plumbing l'ixtures to account for losses above and requirements | | 5.1 | 324,000 | | 267,300 |
| Correct ADA non-compliant Casework/Plumbing | | 54 | 267,300 | 0 | 275,000 |
| Replace antiquated equipment at Technology Education Areas (No FF&) | E) | 11 | 275,000 | 0 | |
| Replace ADA non-compliant appliances at Consumer Economies | | 11. | 45,000 | 0 | 45,000 |
| Replace only Gymnasium Equipment & Bleachers | 14 | 0.00 | 145,000 | 0 | 145,000 |
| Alternate to Renovate Old Gymnasium less improvements above | | 5,000 | 345,000 | .0 | 345,000 |
| Alternate to enclose Library and improve Acoustics | | 12,000 | 210,000 | .0 | 210,000 |
| Renovate Health Suite | | 2,000 | 174,000 | 0 | 174,000 |
| Renovate Lower Level Locker Rooms | | 8.8001 | 1,135,200 | 0 | 1,135,200 |
| | | | 42,000 | 0 | 42,000 |
| NBR-Weld return yokes | | | 13,500 | 0 | 13,500 |
| Replace RTU for Science Wing | | | 54,000 | 0 | 54,000 |
| New gas fired domestic water heater system | | | | | 4,845,65 |
| SUBTOTAL | | | | | - |
| Weston Intermediate School | | | | | 1,000 |
| Site recommendations-Re-install ADA Concrete Ramp | | | | | 4,250 |
| Install paved access to bleachers | | | | | 5,100 |
| Install accessible route to synthetic field | | | | | |
| MEP Recommendations-Penhouse Ventilation | | | | | 5,000 |
| High Temperature Exhaust Fans for Data Closets (2) | | | | | 8,000 |
| Add'l Hot Water Generation and Circulating Pumps; remove heat trace | | | | | 68,000 |
| Add new Thermostatic Mixing Valve to Domestic Hot Water System | | | | | 1,500 |
| | | | | | 92,850 |

SUBTOTAL

Priority # 4 = Between fair and poor (years 3 and 4) Items with code issues such as handicapped compliance or otherwise needing more work and impacting other systems.

| Weston High School - 1966 Building | | | | | Total |
|--|-----------------|-----------------------|-----------------|--------------|--------------------------------------|
| Parking Lot Sensor Control | | | | - | 24,000 |
| Site Recommendations-Accessibile Designated ADA Route | | | | | 2.500 |
| Widen North Side Pedestrian Walkway | | | | | 3,500 |
| ADA Designation | | | | | 200 |
| Building Envelope-Clean & Repair PreCast Concrete | | | | | 0 |
| Replace Exterior Windows & Entrances | | | | 12,000 | 904,000 |
| Abate all ACM floor tile | | | | 15,000 | 75.000 |
| | | | | + | 88,000 |
| ADA Compliance-Toilets | | | | 12 | 15,000 |
| Door Entrances & Hardware | | | | 90 | 81,810 |
| Replace Interior Doors (100%) & Frames (20%) | | | | 40,000 | 208,800 |
| floor surfaces | | | | 28,000 | 341,600 |
| Acoustical Ceilings & Lights in Classrooms & Corridors | | | | 2,750 | 9,625 |
| Acoustical Treatment in MEP Areas | | | | 11.822 | 922,116 |
| Renovate Gymnasium incl Bleachers & Equipment | | | | 500 | 120,000 |
| Replace all lockers | | | | 3.235 | 223,215 |
| Renovate Music Rooms including tiered seating/standing | | | | | |
| MEP Recommendations-Exhaust Draft Fans | | | | 0 | 6,000 |
| Adjust Existing Burners for Controlled Fire | | | | 0 | 3,000 |
| Replace Fuel Oil/Blend Pumps & Filters | | | | 0 | 20,000 |
| Video Monitors in Corridors | | | | 0 | 20,000 |
| Install Classroom Occupancy Sensors | | | | 40 | 25,000 |
| SUBTOTAL. | | | | | 3,093,36 |
| Central Office - Annex | | | Central Office | 2001 Annex | Total |
| ADA Provisions and Accessibility to building & playground | | | | | 4,500 |
| ADA Compliance-Toilet Facilies (2) | | | 21,000 | 21,000 | 42,000 |
| Additional Lighting at Exit Door | | | 2,000 | 0 | 2,000 |
| Control Domestic Hot Water Temperature | | | 201 00 00 00 | 1,500 | 1,500 |
| SUBTOTAL | | | | | 50,000 |
| SUBTOTAL | | | | | 24242300 |
| Bus Garage | | | | | Total |
| ADA Compliance-Toilet/Shower Facility | | | | | 40,000 |
| Doors & Hardware | | | | | 3,000 |
| Improved Office Air Conditioning | 4 | | | 200 | 15,000 |
| SUBTOTAL | | | | | 58,000 |
| Total Hall Datie City Canala | 1952/86 | 1952/86 | 1963/86 | 1963 | Total |
| Town Hall /Police Fire Complex | Town Hall | | Fire | Comm. Center | 23000 |
| Site-ADA Parking & Accessible Routes | 15 | 0 | 0 | 0 | 0 |
| New Concrete Stair at rear of Police | | 16,000 | 0 | 0 | 16,000 |
| ADA Compliance-Toilets & turning Radii | 75,000 | 25,000 | 25,000 | 12,000 | 137,00 |
| Stairs & Floor Level Changes | 19,000 | 7,500 | 8,000 | 0 | 34,500 |
| Door Hardware & Geometery | 23,000 | 15,200 | 10,000 | 800 | 49,000 |
| Entrances | 15,000 | 10,000 | 0 | 0 | 25,000 |
| BUTTER BOTH AND | 0 | Ð | 60,000 | 0 | 60,000 |
| Second Floor ADA Accessibility | 12. | | | | |
| Second Floor ADA Accessibility | | | 0 | 0 | 6.000 |
| Additional Sorage Areas-separated from MEP Areas | 6,000 | 0 | | | |
| Additional Sorage Areas-separated from MEP Areas Repair Damages Wall Surfaces & General Refurbishment | 6,000 95,400 | 0 52,000 | 64,200 | 4,300 | 215,90 |
| Additional Sorage Areas-separated from MEP Areas | 6,000 | 0 52,000 18,000 | 64,200 5,000 | | 6.000 215,900 42,500 45,000 |

Library

Total

Priority # 4 = Between fair and poor (years 3 and 4) Items with code issues such as handicapped compliance or otherwise needing more work and impacting other systems.

| Site-ADA Parking & Accessible Routes | | 94 | 1.250 |
|--|--------|-------------|-----------|
| Window Replacement-no 1994 Addition | | | 126,126 |
| Exterior Door Replacement & or Repair-no 1994 Addition | | | 19,080 |
| Exterior Soffits Repair | | | 16,380 |
| Door Hardware & ADA Compliance | | | 4,920 |
| Floor Tile ACM Abatement (w/10 below) | | | 35,000 |
| | | | 5,000 |
| ADA Reception Desk Provisions | | | 40,000 |
| Accessible Mezzanine Access | | | 247,756 |
| SUBTOTAL | | | |
| T. A. Santing Office (Common | Office | Two (2) Car | Total |
| Transfer Station Office/Garage | Garage | Garage | Buildings |
| ADA provision-Accessible Toilet | 6.500 | 0 | 6,500 |
| Butler Aluminum Building | | | |
| New Public Town Garage | | | Total |
| ADA Provisions-Toilet & Shower Facilities | | | 15,000 |
| Kitchen Facility | | | 3,000 |
| SUBTOTAL | | | 18,000 |
| - Maria de M | | | |

Total Amount

13,676,693

Priority # 3 = Fair (years 5 and 6) Not a code related issue, but much deteriorated item that needs attention

| Hurlbutt Elementary School | North | South | East | Core | Total |
|--|---------|---------|---------------|-------------|--------------|
| | House | House | House | Building | Building |
| Site Recommendations-widen existing and add new walkways | 9,750 | 4,875 | 4,875 | 0. | 19,500 |
| New chainlink fencing along Rte 57 | 4,400 | 0 | 0 | 0 | 4,400 |
| nstall curtain drain east side | | 32,500 | 0 | 0 | 32,500 |
| Resurtace XXXXX 150 | 00 | | | 36,000 | 30,000 |
| Automatic Sprinkler System & Ceiling Tile only | 260,290 | 217,351 | 158,201 | 150,335 | 786,178 |
| Repair Damages Wall Surfaces | 52,300 | 5,000 | 6,500 | 2,500 | 66,300 |
| Complete Mechanical, Electrical & Plumbing Recommendations | | | | | 192,000 |
| SUBTOTAL | | | | | 1,130,87 |
| Weston Middle School | | | 1966 | New Gym | Total |
| | | | Middle School | Pool | |
| Reconstruct all Pedestrian Walkways | | | 18,500 | .0 | 18,500 |
| Rebuild Stairs at NW Site | | | 36,000 | 0 | 36,000 |
| Replace Wooden Guardrail at NW corner of Site | | | 6,240 | 0 | 6,240 |
| Provide hard-surfaced walkway from stairs in SW | | | 3,000 | 0 | 3,000 |
| Renovate Courtyards incl Landscaping | | 49,3964 | 114,552 | 0 | 114,552 |
| Clean, Repair & Paint Exterior Soffit | | 9.600: | 95,040 | .0 | 95,040 |
| Clean, Point & Repair Brick Masonry | | 20.400 | 112,200 | 0 | 112,200 |
| Replace Exterior Windows & Entrances | | 6,528 | 592,932 | 0 | 592,932 |
| Install Automatic Sprinklers throughout | | 2000000 | 917,697 | 148.197 | 1.065.89 |
| Repair/replace all Damaged Surfaces | | 358 126 | 93,292 | 0 | 93,292 |
| Repaint all wall surfaces and Doors & Hardware | | 358,126 | 273,582 | 0 | 273,582 |
| Repair, Reglaze & Refinish Existing Display Cases | | 4 | 27,000 | .0 | 27,000 |
| Alternate for New Auditorium | | 0.500 | 2,437,500 | 0 | 2,437,50 |
| Other general refurbishments | | 149.219 | 2,984,380 | 0 | 2,984,38 |
| MEP Recommendations-OBR-Replace Existing Boilers | | 0 | 135,000 | 0 | 135,000 |
| New Drufts for each boiler | | | 13,000 | | 13,000 |
| New Fuel Oil/Blend Pumps & Filters | | | 7,000 | 0 | 7,000 |
| Replace RTU for Wings 'F' & 'G' | | | 110,000 | 0 | 110,000 |
| Add remote switching in New Gymnasium-exterior to lighting panel | | | 18,000 | D | 18,000 |
| Connect Water meter device to BMS | | | 1,000 | 0 | 1,000 |
| SUBTOTAL | | | 1,55000 | 1850 | 8,144,11 |
| SUBTOTAL | 17 | | | | 0.144.1.1 |
| Weston Intermediate School | | | | | Total |
| Connect Water Meter Readings to BMS | | | | | 1,000 |
| Weston High School - 1966 Building | | | | | Total |
| Renovate Courtyards including Landscaping | | | | 35,250 | 334,875 |
| Clean, Repair & Paint Exterior Soffit | | | | 45000 | 13,200 |
| Clean, Point & Repair Brick Masonry | | | | 12,00m | 39,600 |
| Roof Repairs-minor | | | | | 3,000 |
| Refurbish all wall surfaces | | | | 1.101,(101) | 192,500 |
| Replace Glycol type ethlene with prop | | | | | 17,000 |
| Tie-In to Campos BMS | | | | | 1,000 |
| New Air Systems for-Dance Studio | | | | | 12,500 |
| Add Cooling Colil for RTU Wing 'C' | | | | | 12,500 |
| | | | | | 25,000 |
| New Lighting-Café, Library, Art Room | | | | | 22.5 (10.00) |

656,175

SUBTOTAL.

Priority # 3 = Fair (years 5 and 6) Not a code related issue, but much deteriorated item that needs attention

| Repair Bituminous Paving & Curbs | | | 12,000 | | | 38,220 |
|---|--------|----------------------|-------------------|-----------------|----------------------|-----------|
| Concrete Walkway Repair by replacement | | | 600 | | | 7,200 |
| Repair and or Replace Exterior Wood Railing | | | | 3,000 | 0 | 3,000 |
| Replace previously patched floor tile | | | | 0 | 600 | 600 |
| Convert each AHU to VAV | | | | 27,000 | 23,000 | 50,000 |
| Tie-In to Campus BMS | | | | 5,000 | 5,000 | 10,000 |
| Install Occupancy Sensors | | | | 0 | 10,000 | 10,000 |
| SUBTOTAL | | | | | | 119,020 |
| Bus Garage | | | | | | Total |
| New Total Bituminous Paving Replacement | | | | | 0.000,000 | 129,600 |
| Guardrall Separartion & Retaining Wall Reconstruction | | | | | 0 | 18,000 |
| Building Envelope-Window Replacement | | | | | 0 | 32,100 |
| Masonry Joint Repairs | | | | | 0 | 5,000 |
| Wood Trim & Cupola Repairs/Painting | | | | | | 3,750 |
| Refurbish Interior Surfaces-Walls | | | | | | 13,950 |
| Floors | | | | | | 13,750 |
| Normal & Life Safety Lighting Improvents | | | | | | 22,000 |
| SUBTOTAL | | | | | | 238,149 |
| SUBTOTAL | | | | | | |
| Town Hall/Police Fire Complex | | 1952/86 Town Hall | 1952/86 Police | 1963/86 Fire | 1963 Comm. Center | Total |
| | 64600 | - | 0 | 0 . | 0 | 174,730 |
| Pavement Replacement incl. Curbing | 040170 | 7,000 | 5,000 | 6,500 | 1,000 | 19,500 |
| Caulking Masonry Joints | | 10,000 | 5,000 | 7,500 | 1,500 | 24,000 |
| Masonry Re-Pointing | | 74,000 | 16,000 | 48,700 | 0 | 138,700 |
| Replacement Windows | | 7,000 | in Town Hall | | 0 | 7,000 |
| MEP Recommendations-AC Condensing Unit Replacement | | | III I OWIL FIAII | | | 363,930 |
| SUBTOTAL | | | | | | 505,750 |
| Library | | | | | | Total |
| Pavement Replacement incl Curbing | | | | | 25000 | 67,750 |
| Stone Wall Crack Repair | | | | | | 7,500 |
| Damaged Ceiling Tile Repacement (15%) | | | | | | 4,000 |
| Floor Finishes Replacement | | | | | | 60,000 |
| Lighting Fixture Replacement | | 16 | | | | 40,000 |
| Complete MEP Recommendations-Glycol feed System | | | | | | 5,000 |
| SUBTOTAL. | | | | | | 184,250 |
| Transfer Station Office/Garage | | | | Office | Two (2) Car | Total |
| | | | | Garage | Garage | Buildings |
| Building Envelope-masonry walls & wood trim | | | | 7,500 | 0 | 7,500 |
| Butler Aluminum Building | | | | | | Total |
| Building Envelope-misc repairs | | | | | 2,000 | 2,000 |
| Public Town Garage | | | | | | Total |
| | | | | | | 25,000 |
| Building Envelope-Overhead Door Crack Repair | | | | | | 30,000 |
| Mold Abatement, Water Intrusion & Sealing | | | | | | 2,500 |
| Minor Roof Repairs-Cupola & Shed Roof SUBTOTAL | | | | | | 57,500 |
| -70050000000000000000000000000000000000 | | | | Total ton | | 10,904,51 |
| | | | | Total Amou | n C | 10,304,51 |

Priority # 2 = Between fair and good (years 7 and 8) Deteriorated items not needing immediate repair/replacement.

| Juributt Elementary School | North | South | East | Core | Total |
|--|-----------|---------|----------------|-----------------------|---------------------------|
| MDEROGRAPH CONTRACTOR | House | House | House | Building | Building |
| Repair perimeter chainlink fencing | 1,000 | 1,000 | 1,000 | 0 | 3,000 |
| Pave Staff/Teachers Parking Lot | | | | 23,500 | 23,500 |
| surface Paving Mantenance & Repair | 6,000 | 4,300 | 5,100 | 3,000 | 18,600 |
| Storn Water System | 6,000 | 3,000 | 3,500 | 2,500 | 15,000 |
| Complete Mechanical, Electrical & Plumbing Recommendations | | | | | 640,000 |
| SUBTOTAL | | | | | 700,100 |
| Weston Middle School | | | 1966 | New Gym | Total |
| | | | Middle School | Pool | |
| stone dust access to playing fields | | | 1,875 | 0 | 1,875 |
| Add'n Catch Basins to improve drainage | | | 9,200 | O | 9,200 |
| Replace dual fuel burners for improved contoi | | | 2,600 | 0 | 2,600 |
| Remove in Old Boiler Room water softening system | | | 2,500 | 0 | 2,500 |
| SUBTOTAL | | | | V) C= | 16,175 |
| Weston Intermediate School | | | | | Total |
| | | | | 138 | 2,500 |
| Maintenance of Bark Mulch & Paving | | | | | 6,500 |
| New automatic glycol fill system for ACC-2 SUBTOTAL | | | | 9 | 9,000 |
| en e | | | | | Total |
| Weston High School | | | | | 3.000 |
| Reset Catch Basins for Drainage | | | | | 94,000 |
| Air Conditioning for Classrooms (16) | | | | | 97,000 |
| SUBTOTAL | | | | | 31,000 |
| Central Office and Annex | | | Central Office | 2001 Annex | Total |
| Automate Glycol System to Hot Water | | | 4,000 | 3,500 | 7,500 |
| Automatic Fire Protection System | | | 60,287 | 21,903 | 82,190 |
| SUBTOTAL. | | | | | 89.690 |
| Bus Garage | | | | | Total |
| Automatic Fire Protection System | | | | | 27,058 |
| | | 6 | | | |
| Town Hall/Police Fire Complex | 1952/86 | 1952/86 | 1963/86 | 1963 | Total |
| | Town Hall | Police | Fire | Comm. Center | MINISTER |
| Automatic Fire Protection System | 84,655 | 37,807 | 70.686 | 5,459 | 198,600 |
| | | | | | Total |
| Library | | | | 9 | 9,000 |
| | | | | | |
| New Drainage Structures and Adjustments to Existing | | | | (*/ | 27,440 |
| New Drainage Structures and Adjustments to Existing Interior Re-painting | | | | .*/ | |
| New Drainage Structures and Adjustments to Existing Interior Re-painting Complete Automatic Sprinkler System | | | | .*/ | 62,000 |
| Library New Drainage Structures and Adjustments to Existing Interior Re-painting Complete Automatic Sprinkler System SUBTOTAL Transfer Station Office/Corons | | | Office | Two (2) Car | 62,000 |
| New Drainage Structures and Adjustments to Existing Interior Re-painting Complete Automatic Sprinkler System | | | | Two (2) Car | 62,000 98,440 Total |
| New Drainage Structures and Adjustments to Existing Interior Re-painting Complete Automatic Sprinkler System SUBTOTAL. Transfer Station Office/Garage | | | Garage | Two (2) Car Garage | Building |
| New Drainage Structures and Adjustments to Existing Interior Re-painting Complete Automatic Sprinkler System SUBTOTAL | | | | Two (2) Car | 62,000 98,440 Total |

Butler Aluminum Building

Priority # 2 = Between fair and good (years 7 and 8) Deteriorated items not needing immediate repair/replacement

Public Town Garage

Automatic Fire Protection System

Total 58,000

Total Amount

1,305,569

Priority # 1 = Good (years 9 and 10) Minimal work is needed

Hurlbutt Elementary School

| Weston Middle School | 1966 Middle School | New Gym Pool | Total |
|---|-----------------------|-----------------|-------|
| Plumbing-Remove steam to domestic water heat exchangers | 7,000 | 0 | 7,000 |
| Weston Intermediate School | | | |
| Weston High School | | | |
| Central Office and Annex | | | |
| Bus Garage | | | Total |
| Roofing - Minor repairs | | | 3,500 |
| Town Hall/Police Fire Complex | | | |
| Library | | | |
| Transfer Station Office/Garage | | | |
| Butler Aluminum Building | | | |
| Public Town Garage | | | |
| | | | |

10,500

Total Amount



416 Slater Road, P.O. Box 2590, New Britain, CT 06050-2590 Phone: 860-229-0361 A Fax: 860-229-5303